




Lock Out/Tag Out & Verification (Control of Hazardous Energy*)



LOTO is required whenever servicing, maintenance, or modification is being performed on equipment in which the unexpected energization or start-up of the equipment, or the release of stored energy, could cause injury to people or damage to equipment.

- **Trained and authorized to perform LOTO**
- **Every worker adds own lock to LOTO**
- **Reference Pub-3000, Chapter 18**

* Hazardous Energy = Electrical, Mechanical, Chemical, Pressure or Vacuum, Ionizing or Non-ionizing Radiation, Thermal & Other



For additional information contact Keith Gershon, EH&S Division (x4694).